

RV WHOLESALE INSPECTION

Tech: Terry Camper: 2005 Codan Creek
Silver back
Rin 190731

1. Check everything outside
- Seals/gaskets looks good
 - Silicone/Self level Self level and silencing to do. / Done
 - Lights 2 marker lights out
 - Roof & Slide Out Roof roof has patch
 - Tires Date & Condition tires in good shape
 - Bottles NO BOTTLES
 - Awning manual awning
 - Outdoor Kitchen NA
 - Jacks/Leveling System work as they should
 - Notes Roof has patch and I will self level anything that needs it.

Check Everything Working Inside

- Fixed
- Lights 1 light missing closet bedroom rest of lights work
 - A/C works as it should
 - Heat furnace will not light
 - Stove & Oven stove lights, NO oven
 - Microwave & vent hood convection Microwave works.
 - Fridge Gas & Electric Side
 - Plumbing & Pump water pump runs not picking up water
 - Water Heater Gas & Electric Side tankless looks brand new
 - Radio/Speakers Both work well
 - TV NA
 - Awning manual
 - Outlets 1 outlet by Radiodent went / All rest work
 - Fireplace NA
 - Washer/Dryer if Equipped NA
 - Holding Tanks Dumped sensor panel not working
 - Holding Tank Sensors sensor panel not reading
 - Slide Operation Both work well
 - Does it Need Winterized Yes X No

CLEAN IT UP AFTER ALL IS DONE AND DUMP TANKS

- Notes Bedroom slide floor rotten / Back corner of living room front corner soft. Water damage by gooch and window.

- 1) Living room slide wall next to couch water damage under window
- 2) Big slide floor are very soft.
- 3) Bedroom slide floor is very soft entire length.
- 4) Furnace not lighting up ignitor clicks do no flames.
- 5) Water pump wont pick up water. Pans continually
- 6) Sensor panel only shows gally $\frac{1}{3}$ grey shows empty. Fresh Tank full no lights at all same with Black Tank.
7. Furnace is now running stuck fuel valve
- 8 Carbon Detector not working will need replaced